



ISO 9001:2008, ISO 14001:  
2004 & ISPS COMPLIANT PORT

வ.உ.சிதம்பரனார் துறைமுக பொறுப்புக் கழகம்  
व.उ.चिदम्बरनार पत्तन न्यास  
**V.O.CHIDAMBARANAR PORT TRUST**  
(MINISTRY OF SHIPPING, GOVERNMENT OF INDIA)  
ADMINISTRATIVE OFFICE, HARBOUR ESTATE, TUTICORIN 628 004, TAMIL NADU



TRA-OFTCO-CRG-CONVE-A1-20(46643)/D.1409

Date: 15/09/2020

**TRADE NOTICE**

**Sub: Placement of wagons for loading at Coal yard - reg.**

**Ref: Railway Dept. Lr. no. TNHP/Coal yard**

\*\*\*\*\*

It is informed that following conditions are to be fulfilled by the Port User for availing rail cargo related service in the Port.

1. Rail track/siding should be visible at all times during cargo loading/unloading and the cargo shall be stacked in common loading area, atleast 1.5 M away from the railway track. Care shall be taken while working with FEL/equipment while rail cargo handling to prevent any damage to the railway track.
2. Crossing over the railway track is strictly prohibited and violation of safe rail handling.
3. The rail wagons should not be pushed by FEL or any other vehicle/equipment while loading/unloading/ formation

Violation of any of the above directions will attract severe punitive measures, including suspension/revocation of allotments and Stevedoring & Shore Handling license in accordance with Trust Rules & Regulations.

  
**TRAFFIC MANAGER**

**To:**

The President/Secretary

1. Tuticorin Ship Agents Association (TSAA)
2. Tuticorin Customs Brokers' Association (TCBA)
3. Tuticorin Stevedores Association (TSA)
4. All Industries and stakeholders
5. Southern Railways, Tuticorin Harbour

**Copy to:** PS to CPT; PA to Dy.CPT; FA & CAO; CME; CE; All officers of Traffic Dept.; (Sr.DD/EDP with a request to publish in website).