## **PROFORMA**

## **Details of Tender after Evaluation of the Technical Bids**

SI. No	Name of work	NIT No	Date of Technical Bid Opened	Name of the Participated Bidders Through E-Tender	Name of the Qualified Bidder after Evaluation of the Technical Bid	Name of the Disqualified Bidder after Evaluation of the Technical Bid	Reasons for Disqualification
1	Providing and laying vitrified tiles Painting inner and outer wall surface with emulsion and attending Repair Works at Residential Quarters Type-IV in V.O.C Port Trust	20CE / RCM & BMR / 2020- 21 D/1621Dated-08.09.2020	30.09.2020	1.M/S.Johny Engineers & Contractors, Plot No.1 Park town 4th street extn, Madurai – 625017.  2. M/S.Sri Srinivasa Construction, No: 7/374, Mettur Main road, Kuppichipalayam, Kesarimangalam (PO), Bavani (TK), Erode dt638311.  3. Shri. Vengateswara Constructions, No:107/133B, Millerpuram, Tuticorin – 628003.  4. M/S.Maharaja Engineering Contractor, 35/17A21 Madiline Backside,	1.M/S.Johny Engineers & Contractors, Plot No.1 Park town 4th street extn, Madurai – 625017.  2. M/S.Sri Srinivasa Construction, No: 7/374, Mettur Main road, Kuppichipalayam, Kesarimangalam (PO), Bavani (TK), Erode dt638311.  3. Shri. Vengateswara Constructions, No:107/133B, Millerpuram, Tuticorin – 628003.  4. M/S.Maharaja Engineering Contractor, 35/17A21 Madiline Backside,		-

DESTINATION.

Executive Engineer,

Mallenance Division

and Engineering, Department

Croot-file - CIVII - 1-lan haran - PROFORMA

Salem cam, Salem- 636456.	Salem cam, Salem- 636456.	
90A&163 Jailani	5. P.Meeraza, No: 90A&163 Jailani Street, Tuticorin - 628002.	

4