

DETAILS OF THE TENDER AFTER EVALUATION OF THE TECHNICAL BID

Sl. No	Name of work	Tender NIT No	Date of Technical bid opened	Name of the Participated bidders through e-tender	Name of the qualified bidder after evaluation of the technical bid	Name of the disqualified bidder after evaluation of the technical bid	Reasons for Disqualification
1	Filling the undulated area with dredged materials at Coal Stack Yard-I in VOC Port	06CE/HMD/2023-24/D.3024 dated: 16.10.2023	25.10.2023	1. M/s.Shri Venkateswara Constructions, Tuticorin. 2. M/s.GT Construction, Tuticorin.	1. M/s.Shri Venkateswara Constructions, Tuticorin.	1. M/s.GT Construction, Tuticorin.	M/s.GT Construction has not furnished the civil contractor registration certificate as per NIT.

Objection if any, in the above evaluation may be raised within seven days from the issue of this letter or otherwise, it will be treated that the bidders have no objection and Port shall proceed further evaluation for the tender.

CP
15/11/23

EXECUTIVE ENGINEER
Harbour Maintenance Division